



表 1.19 水質樣品檢測報告

		南台灣環境科技股份有限公司				文件編號: FY-R-B-003 版次: 1.2	
		Eurofins Blue Formosa Environmental Technical Co., Ltd.					
		水質樣品檢測報告				專案編號: FY110B5765 報告編號: R1105765B11	
檢測項目	樣品名稱/採樣位置(座標)/採樣時間/樣品編號				檢測方法	單位	備註
	竹溪源頭	竹溪竹溪橋	竹溪河本橋入處	竹溪金湯橋			
	168994/2542403	108707/2541863	168501/2541811	168418/2541737			
	11:30~11:45	11:50~12:05	12:10~12:25	12:40~12:55			
	B110122433	B110122434	B110122435	B110122436			
	檢 測 值						
氫離子濃度指數	8.3	8.4	8.3	8.3	NIEA W424.53A	-	註6
水溫	24.4	26.6	24.8	24.9	NIEA W217.51A	°C	
導電度	721	798	851	848	NIEA W203.51B	umho/cm 25°C	
溶氧	2.5	5.6	3.8	3.6	NIEA W485.52C	mg/L	
懸浮固體	7.5	11.0	17.4	11.8	NIEA W210.58A	mg/L	
生化需氧量	4.7	5.6	5.1	5.8	NIEA W510.55B	mg/L	
化學需氧量	31.0	18.2	40.5	38.9	NIEA W517.53B	mg/L	
總有機碳	6.8	5.8	8.9	8.1	NIEA W532.52C	mg C/L	
氨氮	10.0	13.8	14.1	16.6	NIEA W437.52C	mg/L	
大腸桿菌群	4.9E+5	1.1E+5	3.5E+6	3.1E+6	NIEA E302.55B	CFU/100mL	
以下空白							