

一般性海堤環境清潔維護

112年1月份辦理成果照片


河川局：第十河川局

填表日期(西元年/月/日)：2023/2/1

編號	地點	日期	改善前	改善後
1	草里海岸保護工	2022/12/29~30		
				

編號	地點	日期	改善前	改善後
2	西碇河分洪道出口 右岸海岸保護工	2022/12/29		
3	湖海路海岸保護工	2022/12/29		

編號	地點	日期	改善前	改善後
4	中角派出所後海岸 保護工	2022/12/30		
5	草里海岸保護工	2023/01/10~11		

編號	地點	日期	改善前	改善後
				
6	社寮港海堤	2023/01/10		

編號	地點	日期	改善前	改善後
				
7	湖海路海岸保護工	2023/01/11		

編號	地點	日期	改善前	改善後
8	西碇河分洪道出口 右岸海岸保護工	2023/01/12		
9	龍洞海堤	2023/01/15		

編號	地點	日期	改善前	改善後
				
10	榮興海岸保護工	2023/01/16-17		

編號	地點	日期	改善前	改善後
11	大屯溪出口海岸保護工	2023/01/18-19	 A wide-angle photograph of a rocky beach under a cloudy sky. In the foreground, there are dark, smooth rocks and several pieces of driftwood. A person wearing a blue raincoat and a yellow hat is crouching on the rocks, possibly collecting samples or debris. In the background, there is a grassy dune and the ocean.	 A wide-angle photograph of the same rocky beach, showing a significant reduction in debris. The rocks are now mostly clear of driftwood and other trash. The background shows the ocean and a grassy dune under a cloudy sky.