

A detailed topographic map of a river area, likely the Qingcao Lake area in Taichung. The map features numerous contour lines in shades of green and blue, indicating elevation changes. A river flows through the center, with several bridges crossing it. The surrounding land is marked with various symbols for buildings, roads, and other infrastructure. The title '新竹市青草湖水岸環境改善' is prominently displayed in the center in a bold, dark green font.


# 新竹市青草湖水岸環境改善

設計監造單位：預景設計有限公司

富林工程技術顧問有限公司

施 工 廠 商：金春福營造股份有限公司










## [課題一] 缺乏友善人行空間



## [課題二] 現況設施形式繁雜老舊




## [課題三] 水岸邊界生硬




## 01.與周邊活動緊密結合

青草湖與周邊的關係斷裂，造成周邊與湖畔無法為一體性，將周邊景觀與活動連結一起，並打造其景觀整體性。




## 02.連續的步行與無障礙系統

環湖周邊的步行系統不連續，並且多處高程變化，透過系統動線的整理，將環湖的步道的景觀性與連續性結合。



## 03.多樣化的景觀空間

透過環湖景觀地的特性，打造不同的湖岸景觀與活動場域，增加多樣性。



## 04.多樣化的湖岸處理

青草湖環湖步道單調，導致環湖活動不易發生與停留，透過不同的邊界系統、創造一些口袋空間，提供停留與活動。