揚塵防治週報表

110/08/23~110/08/29

本週工項進度及位置 110/08/23~110/08/29







本週工項進度及位置 110/08/23~110/08/29















各區空拍現況



200公頃



第二區

西濱大橋下游



第三區 58號複式斷面



第四區

高鐵橋下游



第五區

西螺大橋上游



110年辦理情形:抑制面積及進度



水覆蓋

達成率

%

KPI **400** 公頃

已完成 公頃



河道整理

達成率

67.2%

KPI 2.5 公里 已完成

1.68公里



綠覆蓋

達成率

272%

KPI

已完成

50 公頃

136公頃



其他覆蓋

達成率

23.5%

KPI

已完成

450公頃 105.90公頃



防洪植栽

達成率

52.5%

KPI

已完成

4公里

2.1公里

