


一般性海堤環境清潔維護

112年4月份辦理成果照片

河川局：第十河川局

填表日期(西元年/月/日)：2023/5/2

編號	地點	日期	改善前	改善後
1	草里海岸保護工	2023/04/10-11		
				

編號	地點	日期	改善前	改善後
2	中角派出所後海岸 保護工	2023/04/11		
3	崩山口海堤	2023/04/12-13		

編號	地點	日期	改善前	改善後
				
4	社寮港海堤	2023/04/14		

編號	地點	日期	改善前	改善後
5	大屯溪出口海岸保護工	2023/04/15-16		
				

編號	地點	日期	改善前	改善後
6	新埔海堤	2023/04/18		
		2023/04/21		