

一般性海堤環境清潔維護

112年6月份辦理成果照片

河川局：第十河川局

填表日期(西元年/月/日)：2023/7/3

編號	地點	日期	改善前	改善後
1	榮興海岸保護工	2023/05/20		
				

編號	地點	日期	改善前	改善後
2	大屯溪出口海岸保護工	2023/05/27		
				

編號	地點	日期	改善前	改善後
3	大屯溪出口海岸保護工	2023/06/15	 <p>The image shows a rocky shoreline with a significant amount of plastic waste, including white and blue bags and other debris, scattered across the dark rocks. The sea is visible in the background under an overcast sky.</p>	 <p>The image shows the same rocky shoreline after cleanup. The plastic waste has been removed, and the beach appears clean and clear. The sea and overcast sky are still visible in the background.</p>
			 <p>The image shows several workers in colorful clothing (pink, purple, blue) actively cleaning the rocky beach. They are seen collecting debris into bags. The sea and overcast sky are in the background.</p>	 <p>The image shows the rocky beach after cleanup, now clean and clear. The background features a grassy hillside and the sea under an overcast sky.</p>

編號	地點	日期	改善前	改善後
4	油車口海堤	2023/06/16		
				

編號	地點	日期	改善前	改善後
5	新埔海堤	2023/06/16		
				

編號	地點	日期	改善前	改善後
6	草里海岸保護工	2023/06/17		
				