

一般性海堤環境清潔維護

112 年 8 月份辦理成果照片

河川局：第十河川局

填表日期(西元年/月/日)：2023/9/3

編號	地點	日期	改善前	改善後
1	洞頂海岸保護工	2023/07/21		
2	海洋大學海堤	2023/07/21		

編號	地點	日期	改善前	改善後
3	番仔澳海岸保護工	2023/07/21		
4	西定河分洪道出口 右岸海岸保護工	2023/08/07		

編號	地點	日期	改善前	改善後
5	員山子分洪出口段 海岸保護工	2023/08/07		
6	湖海路海岸保護工	2023/08/08		

編號	地點	日期	改善前	改善後
6-1	湖海路海岸保護工	2023/08/08		
7	馬崗海堤	2023/08/09-10		



編號	地點	日期	改善前	改善後
7-1	馬崗海堤	2023/08/09-10		
8	鶯歌石海岸保護工	2023/08/09		

編號	地點	日期	改善前	改善後
9	草里海岸保護工	2023/08/11-19		
9-1	草里海岸保護工	2023/08/11-19		

編號	地點	日期	改善前	改善後
9-2	草里海岸保護工	2023/08/11-19		
10	新埔海堤	2023/08/11		

編號	地點	日期	改善前	改善後
10-1	新埔海堤	2023/08/11		
10-2	新埔海堤	2023/08/11		

編號	地點	日期	改善前	改善後
11	卯澳海堤	2023/08/14-15		
11-1	卯澳海堤	2023/08/14-15		

編號	地點	日期	改善前	改善後
12	瑞濱海岸保護工	2023/08/15	 A coastal area with concrete armor units (tetrapods) and a large pile of trash, including plastic bags and debris, scattered along the shore. A person in an orange safety vest is visible near the trash.	 The same coastal area, now clean and free of trash. The concrete armor units are visible, and the surrounding area is clear.
12-1	瑞濱海岸保護工	2023/08/15	 A coastal area with concrete armor units (tetrapods) and a large pile of trash, including plastic bags and debris, scattered along the shore. A person in an orange safety vest is visible near the trash.	 The same coastal area, now clean and free of trash. The concrete armor units are visible, and the surrounding area is clear.

編號	地點	日期	改善前	改善後
13	榮興海岸保護工	2023/08/21-22		
13-1	榮興海岸保護工	2023/08/21-22		