

# 一般性海堤環境清潔維護

## 112年9月份辦理成果照片

河川局：第十分署

填表日期(西元年/月/日)：2023/10/1

| 編號 | 地點       | 日期         | 改善前   | 改善後   |
|----|----------|------------|---|---|
| 1  | 真理村海岸保護工 | 2023/09/20 |  A photograph showing a rocky beach area with a person in a blue shirt and cap cleaning up debris. The background features a concrete sea wall and a green hillside under a clear blue sky.     |  A photograph showing the same rocky beach area after cleanup. The debris has been removed, and the area appears much cleaner. The background features a concrete sea wall and a green hillside under a blue sky with some clouds. |
|    |          |            |  A photograph showing a rocky beach area with debris, including a blue plastic bag and other trash, near a concrete sea wall. The background features a green hillside under a clear blue sky. |  A photograph showing the same rocky beach area after cleanup. The debris has been removed, and the area appears much cleaner. The background features a concrete sea wall and a green hillside under a clear blue sky.           |